SAFE WORK METHOD STATEMENT (SWMS)

Business name

Document: SWMS-001 Rev 1
Prepared: 9 Nov 2026
Review by: 9 Dec 2026
Highest risk after controls: Medium

1. BUSINESS AND JOB DETAILS

Job	Mobile scaffold tower set up and use	**Start date**	9 Nov 2026
Working hours	7:00 am to 3:30 pm	**Trade**	Scaffolding

2. HIGH RISK CONSTRUCTION WORK COVERED BY THIS SWMS

YES	Risk of a person falling more than 2 metres		Work on or near chemical, fuel or refrigerant lines
	Work on a telecommunication tower		Work on or near energised electrical installations or services
	Demolition of an element of a structure that is load-bearing or related to its physical integrity		Work in an area that may have a contaminated or flammable atmosphere
	Likely to involve disturbing asbestos		Work involving tilt-up or precast concrete elements
	Structural alterations or repairs that require temporary support to prevent collapse		Work on, in or next to a road, railway, shipping lane or other traffic corridor in use by traffic other than pedestrians
	Work in or near a confined space		Work in an area with movement of powered mobile plant
	Work in or near a shaft or trench with an excavated depth greater than 1.5 metres		Work in an area with artificial extremes of temperature
	Work in or near a tunnel		Work in or near water or other liquid that involves a risk of drowning
	Use of explosives		Diving work
	Work on or near pressurised gas distribution mains or piping		

3. JOB STEPS, HAZARDS AND CONTROLS

#	Job step	Hazards	Risk before	Controls	Risk after	Responsible
1	Check all parts and the ground, and look up for power lines	Contact with overhead power lines Scaffold collapse or fall from scaffold Rules: WHS Regulation 2011, Part 4.4 Falls, Part 5.1 Plant and r.225 (scaffolds)	**Extreme Possible / Catastrophic**	1.1 Ask the network operator to turn off, move or insulate the lines before work starts. [Eliminate] 1.2 Use non-conductive (fibreglass) ladders near any power lines. [Substitute] 1.3 Mark the safe distance with flags, tape or goal posts and keep all plant and people outside it. [Isolate] 1.4 Keep out of the No Go Zone set by your state and the network operator, or get written approval and a safety observer. In NSW and Qld, untrained people and plant stay at least 3 m from lines on poles up to 132	**Medium Rare / Catastrophic**	Site supervisor

#	Job step	Hazards	Risk before	Controls	Risk after	Responsible
				kV, 6 m up to 330 kV and 8 m above 330 kV. In Victoria the limits differ, and work within 8 m of tower lines needs a spotter and the network operator's permission. [Administrative] 1.5 Use a dedicated spotter whenever plant moves or raises anything near lines. [Administrative] 1.6 Treat all lines as live. If plant touches a line, stay in the cab and keep everyone well away. [Administrative] 1.7 Scaffold is built, altered and taken down only by a competent scaffolder, on a firm base with sole boards and ties. [Engineering] 1.8 Fit guardrails, mid rails and toe boards on every working platform. [Engineering] 1.9 Scaffold collapse or fall from scaffold: see step 4 for the full controls [Administrative]		
2	Build to the instructions with outriggers and guardrails	Scaffold collapse or fall from scaffold Falling from height Rules: WHS Regulation 2011, Part 4.4 Falls, Part 5.1 Plant and r.225 (scaffolds); WHS Regulation 2011, Part 4.4 Falls	**Extreme Likely / Catastrophic**	2.1 Use mobile scaffolds only on firm, level ground with castors locked and outriggers fitted. Never move one with anyone on it. [Engineering] 2.2 Scaffold where a person or object could fall more than 4 metres is built by a licensed scaffolder (High Risk Work Licence). [Administrative] 2.3 Scaffold collapse or fall from scaffold: see step 4 for the full controls [Administrative] 2.4 Do the work from the ground where you can, for example pre-assemble on the ground or use extension poles. [Eliminate] 2.5 Install guardrails or edge protection on all open edges before work starts. [Isolate] 2.6 Use a scaffold, mobile work platform or EWP instead of working off a ladder. [Engineering] 2.7 Where edge protection is not practical, use a fall restraint or fall arrest system on a rated anchor point. [Engineering] 2.8 Everyone working at height holds a White Card and has been briefed on this SWMS before going up. [Administrative] 2.9 Have a written emergency and rescue plan, tested before work starts, so a worker hanging in a harness can be brought down within minutes (WHS Regulations r.80). [Administrative] 2.10 Wear a full body harness with a shock-absorbing lanyard, clipped on at all times when using fall arrest. [PPE]	**Medium Rare / Catastrophic**	Site supervisor
3	Lock the wheels before climbing, climb only on the inside	Scaffold collapse or fall from scaffold Falling from height Rules: WHS Regulation 2011, Part 4.4 Falls, Part 5.1 Plant and r.225 (scaffolds); WHS Regulation 2011, Part 4.4 Falls	**Extreme Likely / Catastrophic**	3.1 Do not use a scaffold over 4 metres until the scaffolder gives a written handover certificate. [Administrative] 3.2 Inspect the scaffold before first use, after any change or bad weather, and at least every 30 days. Record it on the scaffold tag. [Administrative] 3.3 Scaffold collapse or fall from scaffold: see step 4 for the full controls [Administrative] 3.4 Falling from height: see step 2 for the full controls [Administrative]	**Medium Rare / Catastrophic**	Site supervisor
4	Never move it with anyone or anything on it	Scaffold collapse or fall from scaffold Falling tools and materials	**Extreme Possible / Catastrophic**	4.1 Scaffold is built, altered and taken down only by a competent scaffolder, on a firm base with sole boards and ties. [Engineering] 4.2 Fit guardrails, mid rails and toe boards on every working platform.	**Medium Unlikely / Major**	Site supervisor

#	Job step	Hazards	Risk before	Controls	Risk after	Responsible
		Rules: WHS Regulation 2011, Part 4.4 Falls, Part 5.1 Plant and r.225 (scaffolds); WHS Regulation 2011, Part 3.2 (falling objects)		[Engineering] 4.3 Use mobile scaffolds only on firm, level ground with castors locked and outriggers fitted. Never move one with anyone on it. [Engineering] 4.4 Scaffold where a person or object could fall more than 4 metres is built by a licensed scaffolder (High Risk Work Licence). [Administrative] 4.5 Do not use a scaffold over 4 metres until the scaffolder gives a written handover certificate. [Administrative] 4.6 Inspect the scaffold before first use, after any change or bad weather, and at least every 30 days. Record it on the scaffold tag. [Administrative] 4.7 Do not overload platforms. Know the duty rating and keep material stacks over the standards. [Administrative] 4.8 Never remove ties, braces, guardrails or boards. Only the scaffolder alters the scaffold. [Administrative] 4.9 Wear a hard hat and safety boots on and around the scaffold. [PPE] 4.10 Barricade and sign the drop zone under overhead work so nobody walks beneath. [Isolate] 4.11 Fit toe boards, kick plates and mesh screens on scaffolds and edges. [Engineering] 4.12 Use catch fans, debris netting or covered walkways where people pass below. [Engineering] 4.13 Tether hand tools when working at height. [Engineering] 4.14 Keep platforms tidy. Do not stack materials near edges or above toe board height. [Administrative] 4.15 Lower materials with a hoist, chute or rope. Never throw or drop anything down. [Administrative] 4.16 Wear a hard hat anywhere objects could fall. [PPE]		
5	Dismantle in reverse order and store parts	Lifting and carrying heavy loads Rules: WHS Regulation 2011, Part 4.2 Hazardous manual tasks	**High Likely / Moderate**	5.1 Plan to avoid carrying: have materials delivered, and old items picked up, as close as possible to where they are used. [Eliminate] 5.2 Use lighter or smaller loads: order smaller bags and shorter lengths, and drain or break down old items before moving them. [Substitute] 5.3 Use trolleys, pallet jacks, hoists, vacuum lifters or plant instead of carrying by hand. [Engineering] 5.4 Use a two-person lift for anything heavy, long or awkward. Plan the route first and clear it. [Administrative] 5.5 Keep the load close, back straight and no twisting. Turn with your feet. [Administrative] 5.6 Rotate tasks and take breaks on long lifting jobs. [Administrative] 5.7 Wear gloves for grip and safety boots to protect your feet. [PPE]	**Medium Unlikely / Moderate**	Site supervisor

Risk key: risk = likelihood x consequence on a 5 x 5 matrix. Low, Medium, High, Extreme. Work must not start while the risk after controls is high or above. Controls are listed in order of the hierarchy of control: Eliminate, Substitute, Isolate, Engineering, Administrative, PPE.

4. PPE AND PERMITS

Required PPE	Permits and plans

Required PPE	Permits and plans
Steel cap boots Hard hat Work gloves Hi-vis shirt or vest Safety glasses	Working at heights permit

5. PLANT AND EQUIPMENT

Plant / equipment	Licence or training needed	Inspection needed	Rego / ID	Last inspected	Certificate / report
Mobile scaffold	Scaffolding HRWL (SB or higher) to erect, alter or dismantle where a person or object could fall more than 4 m	Check before each use to the manufacturer. Over 4 m: written handover certificate before first use (WHS Regulations r.225(2)), then inspected before use after any incident, alteration or repair and at least every 30 days (r.225(3))			
Hand tools					

6. CREW COMPETENCY, TICKETS AND LICENCES

Crew listed at sign-on below, with ticket and licence numbers.

7. EMERGENCY ARRANGEMENTS

Emergency number	000	**First aid kit**	In the work vehicle
Fire extinguisher	In the work vehicle	**Alarm and evacuation**	Shout for help and stop work. Make the area safe and go to the assembly point. Call the emergency number and send someone to meet the ambulance.
Reporting incidents	Notify the regulator immediately of any notifiable incident and preserve the site.		

8. IMPLEMENTING, MONITORING AND REVIEWING THE CONTROLS

How they are put in place	Controls are set up before the work starts. The person responsible explains this SWMS to every worker before they start, and workers sign to confirm they understand it.	**How they are monitored**	The person responsible checks the controls are in place before work starts each day and during the work, and talks to the workers about any problems. Stop work and review this SWMS if the work changes, the controls are not working, after any incident, or if a worker raises a concern.
When it is reviewed	Reviewed when the work or site changes, after any incident, if a control is not working, or if a worker or health and safety representative asks.		

Legal basis: Work Health and Safety Regulations 2011, Part 6.3 (Victoria: OHS Regulations 2017). A SWMS must be prepared before any high risk construction work starts. It must list the high risk work, the hazards and risks, the control measures, and how those controls will be put in place, monitored and reviewed. It must be easy for the workers to read and understand.

Keep this SWMS, and every revised version, until the high risk construction work is finished, where workers and inspectors can see it on site. If a notifiable incident happens during the work, keep it for at least 2 years after the incident.

9. REVIEW AND AMENDMENT RECORD

Rev	Date	By	What changed
1	9 Nov 2026		First issue

10. SIGN-OFF

	Name	Signature	Date	
Prepared by				
Person responsible (supervisor)				
Principal contractor review				Accepted for use: Yes / No

By signing below, each worker confirms they were consulted on and have read and understood this SWMS, and will follow it. If the work cannot be done as this SWMS says, stop as soon as it is safe and do not restart until the SWMS is reviewed.

Name	Role / company	Tickets / licences	Inducted	Signature	Date

Name	Role / company	Tickets / licences	Inducted	Signature	Date